



---

## Project Information

Prepared By: Steve Kaufman

Project Name: E911

Sensor Info: na

Sensor Resolution: 0.5

Vendor Name: Floodplain

Date of Aquisition: Start: 3/18/2011 Finish: 3/18/2011

---

## Metadata Information

Index File Name: Pamlico2010\_index.shp

# of Polygons: 508

# of Matching Images: 508

Polygon ID: location

Units: Feet


Image Folder Path: H:\Pamlico2010\Imagery\TIF

Threshold: CE90: 1.571

Scaling Used: 1:150


---

## Tiled-Image Area






## Vector Offset



Scaling Factor: 10000

## Circular Error



## Error Statistics

Min $\Delta X$ :	-1.063	Min $\Delta Y$ :	-1.063	SX:	0.9
Max $\Delta X$ :	2.322	Max $\Delta Y$ :	0.76	SY:	0.565
Mean $\Delta X$ :	-0.013	Mean $\Delta Y$ :	-0.002	SH:	0.732
Skew $\Delta X$ :	1.642	Skew $\Delta Y$ :	-0.599		
RmseX:	0.619	RmseY:	0.391	RmseH:	0.732
SRMSE H:	0.136				
CE 90:	1.571	CE 95:	1.792	CI:	0.267
No. Observations:	29				
Horiz. Bias:	0.013		NSSDA:	1.236	