



Project Information

Prepared By: Steve Kaufman

Project Name: E911

Sensor Info: na

Sensor Resolution: 0.5

Vendor Name: Floodplain

Date of Aquisition: Start: 3/24/2011 Finish: 3/24/2011

Metadata Information

Index File Name: Stanly2010_index.shp

of Polygons: 522

of Matching Images: 522

Polygon ID: location


Units: Feet

Image Folder Path: H:\Stanly2010\Imagery\TIF

Threshold: CE90: 2.502


Scaling Used: 1:150

Tiled-Image Area






Vector Offset



Scaling Factor: 10000

Circular Error



Error Statistics

Min ΔX :	-1.237	Min ΔY :	-1.628	SX:	1.676
Max ΔX :	4.492	Max ΔY :	1.15	SY:	0.655
Mean ΔX :	-0.247	Mean ΔY :	0.026	SH:	1.166
Skew ΔX :	3.476	Skew ΔY :	-0.932		
RmseX:	1.048	RmseY:	0.469	RmseH:	1.148
SRMSE H:	0.213				
CE 90:	2.502	CE 95:	2.853	CI:	0.417
No. Observations:	30				
Horiz. Bias:	0.249		NSSDA:	1.856	