



---

## Project Information

Prepared By: Steve Kaufman

Project Name: E911

Sensor Info: na

Sensor Resolution: 0.5

Vendor Name: Floodplain

Date of Aquisition: Start: 3/18/2011 Finish: 3/18/2011

---

## Metadata Information

Index File Name: Transylvania2010\_index.shp

# of Polygons: 501

# of Matching Images: 501

Polygon ID: location

Units: Feet


Image Folder Path: H:\Transylvania2010\Imagery\TIF

Threshold: CE90: 2.513

Scaling Used: 1:150


---

## Tiled-Image Area






### Vector Offset



Scaling Factor: 10000

### Circular Error



### Error Statistics

Min $\Delta X$ :	-1.454	Min $\Delta Y$ :	-1.584	SX:	1.084
Max $\Delta X$ :	0.716	Max $\Delta Y$ :	1.671	SY:	1.258
Mean $\Delta X$ :	-0.382	Mean $\Delta Y$ :	-0.169	SH:	1.171
Skew $\Delta X$ :	-0.297	Skew $\Delta Y$ :	0.787		
RmseX:	0.586	RmseY:	0.794	RmseH:	0.987
SRMSE H:	0.214				
CE 90:	2.513	CE 95:	2.866	CI:	0.419
No. Observations:	30				
Horiz. Bias:	0.418		NSSDA:	1.689	